

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Component	G-LTZY	62/21/00/000/000/860 - P/N: C622A1002103 - S/N: M94 - Main Rotor Hub - ALS - AMM 62-21-00, 6-1 - Rotor hub - Damper attachment area - Pt No: C622A1002103 (-), C622A1002104 (-), C622A1002105 (-) - Visual check of absence of crack - VC	15 Hrs	2491 Hrs 30 mn	5 Hrs 22 mn
Component	G-LTZY	62/21/00/000/000/760 - P/N: E4069F12 (7050A3622044) - S/N: 0362 - Lead lag damper - Metallic part - ALS - AMM 05-30-00, 6-1 - Lead lag damper - Elastomer part - Pt No: E4069F12 (7050A3622044), E4069F22 (7050A3622059) - Check - GVI	15 Hrs	2491 Hrs 30 mn	5 Hrs 22 mn
Component	G-LTZY	62/21/00/000/000/760 - P/N: E4069F12 (7050A3622044) - S/N: 0361 - Lead lag damper - Metallic part - ALS - AMM 05-30-00, 6-1 - Lead lag damper - Elastomer part - Pt No: E4069F12 (7050A3622044), E4069F22 (7050A3622059) - Check - GVI	15 Hrs	2491 Hrs 30 mn	5 Hrs 22 mn
Publication	G-LTZY	2021-0069 - A - AD: 2021-0069 - EASB EC120-05A020 - Tail Rotor – Hub Body – Inspection / Replacement - EASA AD 2021-0069 and Emergency ASB EC120-05A020 - Tail Rotor – Hub Body – Inspection / Replacement - Inspect each affected part in accordance with the instructions of section 3.B.2 of the ASB	15 Hrs	2491 Hrs 30 mn	5 Hrs 22 mn
Component	G-LTZY	62/21/00/000/000/760 - P/N: E4069F12 (7050A3622044) - S/N: 0345 - Lead lag damper - Metallic part - ALS - AMM 05-30-00, 6-1 - Lead lag damper - Elastomer part - Pt No: E4069F12 (7050A3622044), E4069F22 (7050A3622059) - Check - GVI	15 Hrs	2491 Hrs 30 mn	5 Hrs 22 mn
Package	ENG S/N - 34032	400H Inspection ARS2F - 40002 - 73-15-00-900-801 - No Ref - Replacement of the RH Main fuel injector half manifold	400 Hrs	2378 Hrs 42 mn	13 Hrs 16 mn
Package	ENG S/N - 34032	400H Inspection ARS2F - 40003 - 73-15-00-900-801 - No Ref - Replacement of the LH Main fuel injector half manifold	400 Hrs	2378 Hrs 42 mn	13 Hrs 16 mn
Package	ENG S/N - 34032	400H Inspection ARS2F - 40001 - 73-15-00-900-801 - No Ref - Replacement of the preference injector pipe	400 Hrs	2378 Hrs 42 mn	13 Hrs 16 mn
Component	G-LTZY	63/22/00/000/000/640 - P/N: C632A0201052 (C632D0201053) - S/N: M237 - Main module Assy (Main Gearbox) (MGB MAIN MODULE) - MSM - AMM 12-10-00, 3-2 & AMM 63-22-00, 3-1 - MGB - After the introduction to service of a new, overhauled or repaired component - Drain and replace the MGB oil filter - DRN	30 Hrs	2502 Hrs 24 mn	16 Hrs 16 mn

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Component	G-LTZY	65/21/00/000/000/500 - P/N: C652A0101055 - S/N: M1595 - Tail Gearbox (TAIL GEARBOX) - MSM - AMM 12-10-00, 3-2 - TGB - After the introduction to service of a new, overhauled or repaired component - Draining - DRN	30 Hrs	2502 Hrs 24 mn	16 Hrs 16 mn
Component	G-LTZY	63/22/00/000/000/640 - P/N: AMP TASK - Post maintenance check - MSM - AMM 12-10-00, 3-2 & AMM 63-22-00, 3-1 - MGB - After the introduction to service of a new, overhauled or repaired component - Drain and replace the MGB oil filter - DRN	30 Hrs	2502 Hrs 24 mn	16 Hrs 16 mn
Component	ENG S/N - 34032	ARS2F - 7101 - P/N: 0319008000 - S/N: 34032 - ENGINE - MM Chap 71-01-00-610-801-A01 and Task 71-01-03-610-801 - Carry out engine chemical cleaning	100 Hrs	2408 Hrs 12 mn	42 Hrs 46 mn
Publication	ENG S/N - 34032	SL 3052/23/ARS2 - ARRIUS 2, all variants Chafing on the fuel injection manifolds - Safran Helicopter Engines noticed several chafing occurrences on the fuel injection manifolds Carry out a visual Inspection of the areas affected by chafing iaw SL	100 Hrs	2408 Hrs 12 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 65/11/00/000/000/100 - MSM - AMM 65-11-00, 6-19 - TAIL ROTOR DRIVE SHAFT - Tail Rotor Drive Shaft - Cover plate - Visual check - VC	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 62/31/00/000/000/100 - MSM - AMM 62-31-00, 3-1 - SWASHPLATE ASSEMBLY - Swashplate - Greasing - LUB	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 56/11/00/000/000/000 - MSM - AMM 56-11-00, 6-2 & AMM 56-11-00, 6-2 & AMM 56-31-00, 6-1 - No Ref - Check transparent panels. After SB 56-002	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 63/00/00/000/000/050 - MSM - AMM 20-10-00, 3-6 - MAIN ROTOR DRIVE - MGB - Chip detector - Check - FT DI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 65/11/00/000/000/750 - MSM - AMM 65-11-00, 3-1 - TAIL ROTOR DRIVE SHAFT - Tail Rotor Drive Shaft - Bearing - Greasing - LUB	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 63/11/00/000/000/210 - MSM - AMM 63-11-00, 6-7 - MGB / ENGINE COUPLING - (NOTE: SAFETY CRITICAL TASK) - Arm assy ball joint - Play check - DI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 65/21/00/000/000/250 - MSM - AMM 20-10-00, 3-6 - TAIL GEARBOX - TGB - Chip detector - Inspection - FT DI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Package	G-LTZY	100H/12M Inspection 65/11/00/000/000/850 - MSM - AMM 65-11-00, 6-4 - TAIL ROTOR DRIVE SHAFT - Tail Rotor Drive Shaft - Flexible coupling - Visual check - VC	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 32/17/00/000/000/010 - MSM - AMM 32-17-00, 6-2 - LANDING GEAR - SKIS - Ski - Detailed check - DI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 62/21/00/000/000/770 - MSM - AMM 62-21-00, 3-1 - MAIN ROTOR HUB - Anti-vibrator - Greasing - LUB	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection FA01 - EQUIPMENT AND FURNISHINGS - First Aid Kit - Check contents and replenish/replace as required - Re-label with next inspection date	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 64/21/00/000/000/100 - MSM - AMM 64-21-00, 6-2 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Blades / Shroud - Play checks - DI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 56/11/00/000/000/000 - MSM - AMM 56-11-00, 6-2, AMM 56-11-00, 6-3 and AMM 56-31-00, 6-1 - CABIN TRANSPARENT PANELS - Transparent panel - Check - GVI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 62/21/00/000/000/765 - MSM - AMM 62-21-00, 4-2 - MAIN ROTOR HUB - Droop Restrainer Ring - Greasing - LUB	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 64/21/00/000/000/150 - MSM - AMM 64-21-00, 6-4 to AMM 64-21-00, 6-16 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail rotor hub - Removal of fairing and visual check of all components without disassembly - DI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 25/22/00/000/000/010 - MSM - AMM 25-22-00, 6-2 - PASSENGERS SEATS - Bench harnesses - Pt No: FHEC1-310002-01 (7050A3252003), FHEC1-31EC03-01 (7050A3252010) - Check - DI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 63/51/00/000/000/050 - MSM - AMM 63-51-00, 5-1 - ROTOR BRAKE - Rotor Brake - Starting Interlock - Functional test - FT	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Package	G-LTZY	100H/12M Inspection 52/33/00/000/000/000 - MSM - AMM 52-33-00, 6-1 - DOORS - PANEL OF COMMUNICATION - Communicating panel between cabin and cargo compartment - Pt No: C523S3101051 (C523S3101051), C523S3101052 (C523S3101052) - PRE SB 53-019 - Condition check - (To be carried out on the aircraft with rear bench removed) - GVI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 63/11/00/000/000/050 - MSM - AMM 63-11-00, 6-3 - MGB / ENGINE COUPLING - Flexible coupling - Visual check - GVI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 25/21/00/000/000/010 - MSM - AMM 25-21-00, 6-2 - CREW SEATS - Pilot and copilot harnesses - Pt No: 159110 (7050A4252005), 1591718-04 (7050A4252001), 1591718-06 (7050A4252012) - Check - DI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	G-LTZY	100H/12M Inspection 64/21/00/000/000/050 - MSM - AMM 64-21-00, 6-1 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Blade / Bearings - Play checks - DI	100 Hrs	2528 Hrs 54 mn	42 Hrs 46 mn
Package	ENG S/N - 34032	100H/12M Inspection ARS2F - 10001 - Refer to Flight Manual - No Ref - Perform a Power check - A2B Aero plot figures on trend graph 20 degree change in 50 hours causes engine rejection.	100 Hrs	2408 Hrs 12 mn	42 Hrs 46 mn
Component	G-LTZY	24/36/01/000/000/000 - P/N: 7050A4243037 - S/N: 1618XL2 - Starter Generator - MSM - AMM 24-36-01, 6-1, AMM 24-36-01, 6-2, AMM 24-36-01, 6-4, AMM 24-36-01, 6-5 - (NOTE: SAFETY CRITICAL TASK) - Starter generator - Pt No: 160SG140Q-1 (7050A4243037) and 160SG140Q-1-XL (7050A4243050 - SKURKA - Checking generator, brushes, damping system and splines - DI TCK	300 Hrs	2569 Hrs 18 mn	83 Hrs 10 mn
Package	ENG S/N - 34032	150H Inspection ARS2F - 15006 - 71-02-08-280-801 - No Ref - Oil sampling for SOA - (PRE TF 78, PRE TF 79)	150 Hrs	2458 Hrs 12 mn	92 Hrs 46 mn
Package	ENG S/N - 34032	150H Inspection ARS2F - 15005 - 72-00-00-200-801 - No Ref - Turbine casing. Inspection of the FCU supply boss - (Pre TF 15)	150 Hrs	2458 Hrs 12 mn	92 Hrs 46 mn
Package	ENG S/N - 34032	150H Inspection ARS2F - 15004 - 72-00-00-200-801 - No Ref - Turbine casing. Inspection of the two P3 bleed air tapping bosses (for aircraft manufacturer's use) - (Pre TF 8)	150 Hrs	2458 Hrs 12 mn	92 Hrs 46 mn

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Package	ENG S/N - 34032	150H/12M Inspection ARS2F - 15002 - 79-38-00-200-801 - No Ref - Electrical magnetic plugs - Visual inspection and check	150 Hrs	2458 Hrs 12 mn	92 Hrs 46 mn
Package	ENG S/N - 34032	150H/12M Inspection ARS2F - 15003 - 79-38-00-110-801 - No Ref - Electrical magnetic plugs - cleaning	150 Hrs	2458 Hrs 12 mn	92 Hrs 46 mn
Package	ENG S/N - 34032	150H/12M Inspection ARS2F - 15001 - 26-11-00-200-801 - No Ref - Visual inspection of fire detectors	150 Hrs	2458 Hrs 12 mn	92 Hrs 46 mn
Package	ENG S/N - 34032	150H/12M Inspection ARS2F - 15007 - 12-10-20-610-801 - No Ref - Oil change according to the SOA results - (In case of a Spectrometric Oil Analysis (A.S.H.) done)	150 Hrs	2458 Hrs 12 mn	92 Hrs 46 mn
Component	G-LTZY	ICA-3201 - P/N: D120-639-011 - S/N: N/A - Dart Skid Wear plates (ICA) - Dart Aerospace Ltd Doc: ICA-D120-639 Para 5.1 - Wearplate Kits - Carry out 300Hr Inspection	300 Hrs	2728 Hrs 54 mn	242 Hrs 46 mn
Package	ENG S/N - 34032	600H Inspection ARS2F - 60009 - 79-24-05-900-802 - No Ref - Replacement of the oil filtering element	600 Hrs	2635 Hrs 48 mn	270 Hrs 22 mn
Package	ENG S/N - 34032	600H Inspection ARS2F - 60014 - 71-02-30-280-803 - No Ref - HP gas-generator turbine front zone - Borescopic inspection	600 Hrs	2635 Hrs 48 mn	270 Hrs 22 mn
Package	ENG S/N - 34032	600H Inspection ARS2F - 60015 - 71-02-30-280-804 - No Ref - HP gas-generator turbine rear zone and power turbine front zone - Borescopic inspection	600 Hrs	2635 Hrs 48 mn	270 Hrs 22 mn
Package	ENG S/N - 34032	600H Inspection ARS2F - 60013 - 71-02-30-280-806 - No Ref - Centrifugal diffuser - Borescopic inspection	600 Hrs	2635 Hrs 48 mn	270 Hrs 22 mn
Package	ENG S/N - 34032	600H Inspection ARS2F - 60017 - 71-02-30-280-802 - No Ref - Borescopic inspection of the combustion chamber	600 Hrs	2635 Hrs 48 mn	270 Hrs 22 mn
Package	ENG S/N - 34032	600H Inspection ARS2F - 60011 - 73-34-00-750-801 - No Ref - Low fuel pressure switch - tests	600 Hrs	2635 Hrs 48 mn	270 Hrs 22 mn
Package	ENG S/N - 34032	600H Inspection ARS2F - 60012 - 79-24-05-900-803 - No Ref - (NOTE: SAFETY CRITICAL TASK) - Replacement of the fuel filtering element	600 Hrs	2635 Hrs 48 mn	270 Hrs 22 mn
Package	ENG S/N - 34032	600H Inspection ARS2F - 60007 - 72-00-42-200-803 - No Ref - Free Turbine - Visual inspection	600 Hrs	2635 Hrs 48 mn	270 Hrs 22 mn
Publication	ENG S/N - 34032	2005-088 - AD: F-2005-088 - ASB A319 73 4823 - Check of correct position of adjusted FCU fuel filter - DGAC AD F-2005-088 and ASB A319734823 - Check of the correct position of the adjusted FCU fuel filter	500 Hrs	2799 Hrs 54 mn	434 Hrs 28 mn

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Component	G-LTZY	P/N: 421722-8 - S/N: N/A - Steerable Landing Light (ICA) - Carry out functional check iaw AMM 33-44-01,5-1	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 63/51/00/000/000/100 - MSM - AMM 63-51-00, 6-1 - ROTOR BRAKE - Rotor brake - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/32/00/000/000/370 - MSM - AMM 62-32-00, 6-4 - FLARED HOUSING / SWASHPLATES / HUB COUPLINGS - (NOTE: SAFETY CRITICAL TASK) - Pitch change rod - Detailed check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 65/11/00/000/000/900 - MSM - AMM 65-11-00, 6-15 - TAIL ROTOR DRIVE SHAFT - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Drive Shaft - Flexible Coupling Attachment - Detailed check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/32/00/000/000/360 - MSM - AMM 62-32-00, 6-2 - FLARED HOUSING / SWASHPLATES / HUB COUPLINGS - Scissor link - Check - In the case of default constated inside the rings of the scissor link (inside the limits) make sure of the absences of the following hard points CT 62-32-00, 6-7 every 100 FH (marge 10 FH) - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 21/00/00/000/000/000 - MSM - AMM 21-41-00, 5-1 - AIR CONDITIONING - P2 Indicating System - Functional test - FT - (Very cold weather)	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/21/00/000/000/790 - MSM - AMM 62-21-00, 6-2 to AMM 62-21-00, 6-20 - MAIN ROTOR HUB - Main rotor hub - Visual check without removal - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/32/00/000/000/350 - MSM - AMM 62-32-00, 6-1 - FLARED HOUSING / SWASHPLATES / HUB COUPLINGS - (NOTE: SAFETY CRITICAL TASK) - "Diapason" scissors - Ball joint - Play check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 52/11/00/000/000/050 - MSM - AMM 52-11-00, 5-1 - RIGHT CABIN DOOR - Jettison System RH Cabin Door - Functional test - FT	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 67/20/00/000/000/100 - MSM - AMM 67-20-00, 6-1 - TAIL ROTOR CONTROLS - Tail rotor controls - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 28/00/00/000/000/050 - MSM - AMM 28-00-00, 6-1 - FUEL SYSTEM - Fuel system - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Package	G-LTZY	500H/24M Inspection 62/21/00/000/000/795 - MSM - AMM 62-21-00, 6-26 - MAIN ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Split Ring - POST SB 62-010 or from SN 1393 and 8009 (factory applied modification) - Detailed check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 24/00/00/000/000/100 - MSM - AMM 24-00-00, 6-1 - ELECTRICAL POWER - Electrical Power Supply System - Inspection - VC	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/21/00/000/000/780 - MSM - AMM 62-21-00, 6-2 and AMM 63-21-00, 6-2 - MAIN ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Main Rotor Hub - Contact areas between Rotor Shaft and Hub Body - Check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 52/10/00/000/000/100 - MSM - AMM 52-10-00, 6-1 - STANDARD CABIN DOORS - Standard Cabin Door - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 53/50/00/000/000/250 - MSM - AMM 20-10-00, 6-1 and AMM 53-50-00, 4-1 - AFT FUSELAGE - (NOTE: SAFETY CRITICAL TASK) - Main fuselage and tail boom junction - Tightening torque check - TCK	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 65/21/00/000/000/400 - MSM - AMM 65-21-00, 6-1 - TAIL GEARBOX - TGB - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 65/11/00/000/000/800 - MSM - AMM 65-11-00, 6-3 - TAIL ROTOR DRIVE SHAFT - Tail Rotor Drive Shaft - Damper and contact surface on drive shaft - Check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 79/21/00/000/000/050 - MSM - AMM 79-21-00, 6-1 - ENGINE OIL COOLING - Engine Oil - Oil cooling system - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/31/00/000/000/160 - A - MSM - AMM 62-31-00, 6-6 - SWASHPLATE ASSEMBLY - Rotating washplate - Pt No: 7050A3623019 (7050A3623019) - Inspection of free rotation - Operation to be done every 100 FH (margin 10 FH) between 3300 FH and 5300 FH from the OTL - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 24/33/00/000/000/100 - MSM - AMM 24-33-00, 5-1 - BATTERY - Battery temperature detector - Functional test - FT	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Package	G-LTZY	500H/24M Inspection 21/00/00/000/000/010 - MSM - AMM 21-21-00, 6-1 - AIR CONDITIONING - P2 Indicating System - Check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 53/53/00/000/000/150 - MSM - AMM 20-10-00, 6-1 and AMM 53-53-00, 4-1 - FENESTRON - (NOTE: SAFETY CRITICAL TASK) - Tail Boom and Fenestron Junction - Tightening torque check - TCK	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 28/00/00/000/000/060 - MSM - AMM 28-00-00, 6-3 - FUEL SYSTEM - Fuel System - Strainers - Check and cleaning - DI CLN	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 63/22/00/000/000/650 - MSM - AMM 12-10-00, 3-2 and AMM 63-22-00, 3-1 - MGB MAIN MODULE - MGB - Drain and replace the MGB oil filter - DRN	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/11/00/000/000/160 - MSM - AMM 62-11-00, 6-4 - MAIN ROTOR BLADES - Main Rotor Blades - Attachment Components - Detailed check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 67/31/00/000/000/150 - MSM - AMM 20-10-00, 6-1 and AMM 67-31-00, 4-2 - SERVOCONTROLS - Servocontrol - Tightening torque check of the attachment bolts - TCK	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 55/11/00/000/000/000 - MSM - AMM 55-11-00, 6-1 - HORIZONTAL STABILIZER - (NOTE: SAFETY CRITICAL TASK) - Horizontal Stabilizer - Detailed check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 34/00/00/000/000/050 - MSM - AMM 34-00-00, 6-1 - NAVIGATION - Navigation System - Installation check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 63/11/00/000/000/100 - MSM - AMM 12-10-00, 6-1 and AMM 63-11-00, 4-2 - MGB / ENGINE COUPLING - (NOTE: SAFETY CRITICAL TASK) - Ball joint bolt - Tightening torque check - TCK	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 33/00/00/000/000/050 - MSM - AMM 33-00-00, 6-1 - LIGHTING SYSTEMS - Lighting System - Installation check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 53/00/00/000/000/200 - MSM - AMM 53-00-00, 6-1 and AMM 53-00-00, 6-2 - FUSELAGE - Fuselage - Visual check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn



# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Package	G-LTZY	500H/24M Inspection 62/32/00/000/000/400 - MSM - AMM 62-32-00, 6-5 - FLARED HOUSING / SWASHPLATES / HUB COUPLINGS - (NOTE: SAFETY CRITICAL TASK) - Scissor bolt - Play checks - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 71/41/00/000/000/200 - MSM - AMM 71-41-00, 6-1 to AMM 71-41-00, 6-11 - ENGINE SUPPORT BRACKET - (NOTE: SAFETY CRITICAL TASK) - Engine support bracket components - Detailed check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 76/12/00/000/000/050 - MSM - AMM 76-12-00, 4-3 - ENGINE CONTROLS - (NOTE: SAFETY CRITICAL TASK) - Engine Controls - Manual Control - Fuel flow ball-type control - Check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 63/52/00/000/000/050 - MSM - AMM 63-52-00, 6-1 - ROTOR BRAKE CONTROL - Rotor brake control - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 21/51/00/000/000/200 - MSM - AMM 21-51-00, 8-1 - COOLING - Belt - Check of tension - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 67/10/00/000/000/050 - MSM - AMM 67-10-00, 6-1 - MAIN ROTOR CONTROLS - Main rotor controls - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/21/00/000/000/840 - MSM - AMM 62-21-00, 6-28 - MAIN ROTOR HUB - Scissors drive coupling / Main rotor hub - Tightening torque check - TCK	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 76/11/00/000/000/000 - MSM - AMM 76-11-00, 6-1 - ENGINE CONTROLS - (NOTE: SAFETY CRITICAL TASK) - Engine Controls - Anticipator control - Ball joint - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 52/10/00/000/000/000 - MSM - AMM 52-10-00, 6-2 / 6-3 / 6-4 - STANDARD CABIN DOORS - Standard Cabin Doors - Inspection/Check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 65/21/00/000/000/300 - MSM - AMM 12-10-00, 3-2 - TAIL GEARBOX - TGB - Oil change - DRN	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 28/42/00/000/000/150 - MSM - AMM 28-42-00, 6-1 - FUEL SYSTEM - Fuel Low-Level Warning - Check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Package	G-LTZY	500H/24M Inspection 52/30/00/000/000/000 - MSM - AMM 52-30-00, 3 -1 - LOADING DOORS - Door lock - Pt No: HA2423-3 (706A31610026) - Check and greasing - DI LUB	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 53/30/00/000/000/300 - MSM - AMM 20-10-00, 6 -1 and AMM 53-30-00, 4-2 - MAIN FUSELAGE - (NOTE: SAFETY CRITICAL TASK) - MGB suspension bar brackets - Tightening torque check - TCK	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 21/51/00/000/000/150 - MSM - AMM 21-51-00, 6 -1 - COOLING - Air conditioning system - Inspection of the installation - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 28/22/00/000/000/100 - MSM - AMM 28-22-00, 5 -1 - FUEL SYSTEM - Fuel Shut-off Valve - Functional test - FT	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 63/11/00/000/000/150 - MSM - AMM 20-10-00, 6 -1 and AMM 63-11-00, 6-6 - MGB / ENGINE COUPLING - (NOTE: SAFETY CRITICAL TASK) - Flexible coupling - Tightening torque check - TCK	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 31/00/00/000/000/050 - MSM - AMM 31-00-00, 6 -1 - INDICATING AND RECORDING SYSTEMS - Indicating and recording system - Check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 21/51/00/000/000/250 - MSM - AMM 20-10-00, 6 -1 and AMM 21-51-00, 8-1 - COOLING - MGB compressor - Tightening torque check of attachment - TCK	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 71/00/00/000/000/100 - MSM - AMM 71-00-00, 6 -1 - POWER PLANT - Power plant installation - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 29/00/00/000/000/050 - MSM - AMM 29-00-00, 6 -1 - HYDRAULIC POWER - Servocontrol - Accumulator - Pressure check - NPT	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/11/00/000/000/150 - MSM - AMM 62-11-00, 6 -1 - MAIN ROTOR BLADES - Main rotor blade - Inspection - Check every 100 FH (marge 10 FH) for 500 FH, if a defect (inside the limits) is found : blade skin separation or blade leading edge stainless steel strip separation, cracks in the stainless steel leading edge. If no development is noted during this period, return to the normal inspection cycle - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Package	G-LTZY	500H/24M Inspection 53/37/00/000/000/000 - MSM - AMM 53-37-00, 6 -1 - CABIN ANTIVIBRATORS - Cabin antivibrator support - Readjustment of the tightening torque - RTQ	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 52/50/00/000/000/210 - MSM - AMM 52-50-00, 6 -2 & 6-3 - SLIDING DOOR - Cabin Sliding Door - Inspection/Check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/31/00/000/000/150 - MSM - AMM 62-31-00, 6 -6 - SWASHPLATE ASSEMBLY - (NOTE: SAFETY CRITICAL TASK) - Rotating swashplate - Inspection of free rotation - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 65/21/00/000/000/350 - MSM - AMM 20-10-00, 6 -1 and AMM 65-21-00, 4-2 - TAIL GEARBOX - TGB / Stator coupling - Tightening torque check - TCK	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 88/00/00/000/000/050 - MSM - AMM 88-00-00, 6 -1 - ELECTRICAL HARNESSSES - Electrical harnesses - Check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 05/22/00/000/000/050 - MSM - FLM Section 8 - PREPARATION FOR INSPECTION - Do a Ground Check - GR	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 52/50/00/000/000/200 - MSM - AMM 52-50-00, 6 -1 - SLIDING DOOR - Cabin Sliding Door - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 62/32/00/000/000/300 - MSM - AMM 62-32-00, 3 -1 - FLARED HOUSING / SWASHPLATES / HUB COUPLINGS - Non-rotating and rotating scissors - Carbide rings - Greasing - LUB	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 23/00/00/000/000/050 - MSM - AMM 23-00-00, 6 -1 - COMMUNICATIONS - Communication System - Inspection - VC	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 63/00/00/000/000/300 - MSM - AMM 63-00-00, 6 -1 - MAIN ROTOR DRIVE - Main rotor drive - Condition check - GVI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	G-LTZY	500H/24M Inspection 76/12/00/000/000/000 - MSM - AMM 12-20-00, 6 -1 - ENGINE CONTROLS - (NOTE: SAFETY CRITICAL TASK) - Engine Controls - Manual Control - Ball end-fitting - L'HOTELLIER - Check - DI	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Hour</b>					
Package	G-LTZY	500H/24M Inspection 52/53/00/000/000/000 - MSM - AMM 52-53-00, 5-1 - LEFT SMALL DOOR - Jettison System LH small cabin door - Functional test - FT	500 Hrs	2928 Hrs 54 mn	442 Hrs 46 mn
Package	ENG S/N - 34032	500H/24M Inspection ARS2F - 50004 - 73-23-00-700-801 - No Ref - Functional point of the hydromechanical governor - Tests	500 Hrs	2808 Hrs 12 mn	442 Hrs 46 mn
Package	ENG S/N - 34032	500H/24M Inspection ARS2F - 50002 - 73-15-00-700-801 - No Ref - Non-extinguishing function - Tests - (Ground Run)	500 Hrs	2808 Hrs 12 mn	442 Hrs 46 mn
Package	ENG S/N - 34032	500H/24M Inspection ARS2F - 50001 - 73-31-00-750-801 - No Ref - Pre-blockage pressure switch of the fuel filter - Tests - (If P/N 9550172880)	500 Hrs	2808 Hrs 12 mn	442 Hrs 46 mn
Package	ENG S/N - 34032	500H/24M Inspection ARS2F - 50003 - 73-14-05-750-801 - No Ref - Sealing test of the start electrovalve - (Ground Run)	500 Hrs	2808 Hrs 12 mn	442 Hrs 46 mn
<b>Calendar</b>					
Publication	G-LTZY	2013-04 - AD: SIB 2013-04R2 - No Subject - Hook and Loop Style Fasteners as Mounting Mechanism for an Emergency Locator Transmitter - EASA SIB 2013-04 R2 - Emergency Locator Transmitter  Carry out check for:  <ul style="list-style-type: none"> <li>• Proper ELT installation;</li> <li>• Battery corrosion;</li> <li>• Operation of the controls and crash sensor; and</li> <li>• The presence of a sufficient signal radiated from its antenna</li> </ul> In addition check textile fasteners for:  <ul style="list-style-type: none"> <li>• Signs of damage</li> <li>• Loss of function, wear, or onset of deterioration over its entire length, especially where contact to other materials (buckles, loops, rings) or where it is glued or welded.</li> </ul>	1 Yr	10/05/2024	10 Days
Component	G-LTZY	ICA-3403 - P/N: 011-00455-00 - S/N: 84145863 - Garmin GTX330 Transponder (ICA) - Gama Engineering Ltd Doc: ICA101701 Issue 2, Para 3.2 - Garmin GTX330 Mode S Transponder - Carry out Annual Inspection	1 Yr	10/05/2024	10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Component	G-LTZY	24/33/00/000/000/060 - P/N: 151CH-1 - S/N: D01649 - Battery - MSM - CMM 24.33.96 CHECK § 7 - Battery - Pt No: 150CH-1 (7050A4243027) 151CH-1 (7050A4243040) 151CH-2 (7050A4243039) - Check - DI	1 Yr	10/05/2024	10 Days
Component	G-LTZY	ICA-3406 - Garmin GTR 225A (ICA) - Gama Aviation Doc: ICA-GNC255(x) Issue 1, Para 4 - Garmin VHF Navigation/Communication Transceiver - 12 Month Inspection - Inspect the structural provision for evidence of: cracks, corrosion, loose rivets, missing protective treatments or any other damage - Visually inspect the installation for mechanical security and connector integrity. Check the condition and routing of electrical cables looking for signs of exposed wires, chafing or missing insulation, adequate security and clamping of cable ties and clips etc	1 Yr	10/05/2024	10 Days
Publication	G-LTZY	2019-09 - AD: SIB: 2019-09 - No Subject - Emergency Locator Transmitters and Personal Locator Beacon - Annual Test and Inspection - EASA SIB 2019-09 - Emergency Locator Transmitters and Personal Locator Beacon - Annual Test and Inspection	1 Yr	10/05/2024	10 Days
Package	G-LTZY	12M Inspection 26/22/00/000/000/075 - MSM - AMM 26-22-00, 6-1 - CABIN EXTINGUISHER - (NOTE: SAFETY CRITICAL TASK) - Cabin fire extinguisher - Pt No: 12085-01 (S262A10T1001) PLA863520-00 (T262M50T0002) - Weighing - TSM - WGH	1 Yr	10/05/2024	10 Days
Package	G-LTZY	12M Inspection 32/12/00/000/000/010 - MSM - AMM 32-12-00, 6-3 - LANDING GEAR - Landing gear - Visual inspection - GVI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 56/11/00/000/000/000 - MSM - AMM 56-11-00, 6-2 & AMM 56-11-00, 6-2 & AMM 56-31-00, 6-1 - No Ref - Check transparent panels. After SB 56-002	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 32/17/00/000/000/010 - MSM - AMM 32-17-00, 6-2 - LANDING GEAR - SKIS - Ski - Detailed check - DI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 65/21/00/000/000/250 - MSM - AMM 20-10-00, 3-6 - TAIL GEARBOX - TGB - Chip detector - Inspection - FT DI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 56/11/00/000/000/000 - MSM - AMM 56-11-00, 6-2, AMM 56-11-00, 6-3 and AMM 56-31-00, 6-1 - CABIN TRANSPARENT PANELS - Transparent panel - Check - GVI	1 Yr	10/05/2024	10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	100H/12M Inspection 62/21/00/000/000/765 - MSM - AMM 62-21-00, 4 -2 - MAIN ROTOR HUB - Droop Restrainer Ring - Greasing - LUB	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 65/11/00/000/000/750 - MSM - AMM 65-11-00, 3 -1 - TAIL ROTOR DRIVE SHAFT - Tail Rotor Drive Shaft - Bearing - Greasing - LUB	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 62/31/00/000/000/100 - MSM - AMM 62-31-00, 3 -1 - SWASHPLATE ASSEMBLY - Swashplate - Greasing - LUB	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 64/21/00/000/000/050 - MSM - AMM 64-21-00, 6 -1 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Blade / Bearings - Play checks - DI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 63/11/00/000/000/210 - MSM - AMM 63-11-00, 6 -7 - MGB / ENGINE COUPLING - (NOTE: SAFETY CRITICAL TASK) - Arm assy ball joint - Play check - DI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 62/21/00/000/000/770 - MSM - AMM 62-21-00, 3 -1 - MAIN ROTOR HUB - Anti-vibrator - Greasing - LUB	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 52/33/00/000/000/000 - MSM - AMM 52-33-00, 6 -1 - DOORS - PANEL OF COMMUNICATION - Communicating panel between cabin and cargo compartment - Pt No: C523S3101051 (C523S3101051), C523S3101052 (C523S3101052) - PRE SB 53-019 - Condition check - (To be carried out on the aircraft with rear bench removed) - GVI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 63/00/00/000/000/050 - MSM - AMM 20-10-00, 3 -6 - MAIN ROTOR DRIVE - MGB - Chip detector - Check - FT DI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 63/11/00/000/000/050 - MSM - AMM 63-11-00, 6 -3 - MGB / ENGINE COUPLING - Flexible coupling - Visual check - GVI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 64/21/00/000/000/150 - MSM - AMM 64-21-00, 6 -4 to AMM 64-21-00, 6-16 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail rotor hub - Removal of fairing and visual check of all components without disassembly - DI	1 Yr	10/05/2024	10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	100H/12M Inspection 64/21/00/000/000/100 - MSM - AMM 64-21-00, 6-2 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Blades / Shroud - Play checks - DI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection FA01 - EQUIPMENT AND FURNISHINGS - First Aid Kit - Check contents and replenish/replace as required - Re-label with next inspection date	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 65/11/00/000/000/850 - MSM - AMM 65-11-00, 6-4 - TAIL ROTOR DRIVE SHAFT - Tail Rotor Drive Shaft - Flexible coupling - Visual check - VC	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 25/21/00/000/000/010 - MSM - AMM 25-21-00, 6-2 - CREW SEATS - Pilot and copilot harnesses - Pt No: 159110 (7050A4252005), 1591718-04 (7050A4252001), 1591718-06 (7050A4252012) - Check - DI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 25/22/00/000/000/010 - MSM - AMM 25-22-00, 6-2 - PASSENGERS SEATS - Bench harnesses - Pt No: FHEC1-310002-01 (7050A3252003), FHEC1-31EC03-01 (7050A3252010) - Check - DI	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 63/51/00/000/000/050 - MSM - AMM 63-51-00, 5-1 - ROTOR BRAKE - Rotor Brake - Starting Interlock - Functional test - FT	1 Yr	10/05/2024	10 Days
Package	G-LTZY	100H/12M Inspection 65/11/00/000/000/100 - MSM - AMM 65-11-00, 6-19 - TAIL ROTOR DRIVE SHAFT - Tail Rotor Drive Shaft - Cover plate - Visual check - VC	1 Yr	10/05/2024	10 Days
Package	ENG S/N - 34032	100H/12M Inspection ARS2F - 10001 - Refer to Flight Manual - No Ref - Perform a Power check - A2B Aero plot figures on trend graph 20 degree change in 50 hours causes engine rejection.	1 Yr	10/05/2024	10 Days
Package	ENG S/N - 34032	150H/12M Inspection ARS2F - 15003 - 79-38-00-110-801 - No Ref - Electrical magnetic plugs - cleaning	1 Yr	10/05/2024	10 Days
Package	ENG S/N - 34032	150H/12M Inspection ARS2F - 15001 - 26-11-00-200-801 - No Ref - Visual inspection of fire detectors	1 Yr	10/05/2024	10 Days
Package	ENG S/N - 34032	150H/12M Inspection ARS2F - 15007 - 12-10-20-610-801 - No Ref - Oil change according to the SOA results - (In case of a Spectrometric Oil Analysis (A.S.H.) done)	1 Yr	10/05/2024	10 Days
Package	ENG S/N - 34032	150H/12M Inspection ARS2F - 15002 - 79-38-00-200-801 - No Ref - Electrical magnetic plugs - Visual inspection and check	1 Yr	10/05/2024	10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Component	G-LTZY	ICA-2504 - P/N: S1852501-02 - S/N: RX1000029672 - Emergency Locator Transmitter (Kannad INTEGRA AF-H) (ELT) - Orolia SAS Ref: DO09078G Rev 06 (03 Sep 2021) Page 301 Para 1A - Emergency Locator Transmitter - AF-H Intergra - Carry out self test	6 Mths	17/05/2024	17 Days
Component	G-LTZY	32/12/00/000/000/100 - Landing Gear - MSM - AMM 32-12-00, 6-2 - Landing Gear - Pt No: C321A2101053 (-) C321A2101054 (-) C321A2501051 (-) C321A2601051 (-) C321A2602052 (-) - POST SB 32-013 - Detailed inspection - Operation to be carried out from 96 M (margin 180 D) from the first installation - DI	4 Yrs	01/08/2024	3 Mths 1 Day
Miscellaneous	G-LTZY	REF: 32746 - Aircraft Radio License - Renew	3 Yrs	31/07/2024	3 Mths 1 Day
Component	G-LTZY	32/12/00/000/000/090 - Landing Gear - MSM - AMM 32-12-00, 6-2 - Landing Gear - Pt No: C321A2101053 (-) C321A2101054 (-) C321A2501051 (-) C321A2601051 (-) C321A2602052 (-) - PRE SB 32-013 - Detailed inspection - Operation to be carried out from 72 M (margin 180 D) from the first installation - DI	4 Yrs	01/08/2024	3 Mths 1 Day
Component	G-LTZY	32/12/00/000/000/070 - Landing Gear - MSM - AMM 32-12-00, 6-2 - Landing Gear - Pt No: C321A2602053 (-) C321A2602054 (-) - Detailed inspection - Operation to be carried out from 144 M (margin 180 D) from the first installation - DI	6 Yrs	01/08/2024	3 Mths 1 Day
Package	G-LTZY	144M Inspection 05/24/00/000/000/000 - MSM - AMM 05-24-00, 6-1 - PREPARATION FOR THE MAJOR INSPECTION - Preparation for the major inspection - Detailed check - DI	12 Yrs	01/08/2024	3 Mths 1 Day
Component	G-LTZY	05/40/00/000/000/010 - P/N: B216100-016 (7050A3633016) - S/N: 172 - MGB forward bar (MGB GEARBOX SUSPENSION) - MSM - AMM 05-40-00, 6-1 - Dynamic systems - Detailed check - Operation to be carried out after having logged 144 M (margin 180 D) after initial setting to service or since the last Overhaul - DI	6 Yrs	17/10/2024	5 Mths 17 Days
Component	G-LTZY	05/40/00/000/000/010 - P/N: B216100-015 (7050A3633015) - S/N: 170 - MGB rear bar (MGB GEARBOX SUSPENSION) - MSM - AMM 05-40-00, 6-1 - Dynamic systems - Detailed check - Operation to be carried out after having logged 144 M (margin 180 D) after initial setting to service or since the last Overhaul - DI	6 Yrs	17/10/2024	5 Mths 17 Days
Component	G-LTZY	05/40/00/000/000/010 - P/N: B216100-015 (7050A3633015) - S/N: 164 - MGB rear bar (MGB GEARBOX SUSPENSION) - MSM - AMM 05-40-00, 6-1 - Dynamic systems - Detailed check - Operation to be carried out after having logged 144 M (margin 180 D) after initial setting to service or since the last Overhaul - DI	6 Yrs	17/10/2024	5 Mths 17 Days



# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Component	G-LTZY	05/40/00/000/000/010 - P/N: AMP TASK - Dynamic systems - MSM - AMM 05-40-00, 6-1 - Dynamic systems - Detailed check - Operation to be carried out after having logged 144 M (margin 180 D) after initial setting to service or since the last Overhaul - DI	6 Yrs	17/10/2024	5 Mths 17 Days
Component	G-LTZY	05/40/00/000/000/010 - P/N: B216100-016 (7050A3633016) - S/N: 175 - MGB forward bar (MGB GEARBOX SUSPENSION) - MSM - AMM 05-40-00, 6-1 - Dynamic systems - Detailed check - Operation to be carried out after having logged 144 M (margin 180 D) after initial setting to service or since the last Overhaul - DI	6 Yrs	17/10/2024	5 Mths 17 Days
Component	G-LTZY	05/40/00/000/000/010 - P/N: C631A1102601 - S/N: SP087 - Shaft connecting (MGB / ENGINE COUPLING) - MSM - AMM 05-40-00, 6-1 - Dynamic systems - Detailed check - Operation to be carried out after having logged 144 M (margin 180 D) after initial setting to service or since the last Overhaul - DI	6 Yrs	17/10/2024	5 Mths 17 Days
Package	G-LTZY	1500H/72M Inspection 65/11/00/000/000/720 - MSM - AMM 65-11-00, 6-20 - TAIL ROTOR DRIVE SHAFT - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Drive Shaft - Cover Plate - Detailed check - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 65/11/00/000/000/300 - MSM - AMM 65-11-00, 6-4 - TAIL ROTOR DRIVE SHAFT - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Drive Shaft - Flexible Coupling - Detailed check - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 62/31/00/000/000/200 - MSM - AMM 62-31-00, 6-6 - SWASHPLATE ASSEMBLY - (NOTE: SAFETY CRITICAL TASK) - Swashplate - Clearance check - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 65/11/00/000/000/710 - MSM - AMM 65-11-00, 6-3 - TAIL ROTOR DRIVE SHAFT - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Drive Shaft - Rear Shaft - Detailed check - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 65/11/00/000/000/450 - MSM - AMM 65-11-00, 6-14 - TAIL ROTOR DRIVE SHAFT - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Drive Shaft - Bearing - Detailed check - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 65/11/00/000/000/350 - MSM - AMM 65-11-00, 6-5 - TAIL ROTOR DRIVE SHAFT - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Drive Shaft - Flexible Coupling bolts - Detailed check - DI	6 Yrs	19/10/2024	5 Mths 19 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	1500H/72M Inspection 25/21/00/000/000/020 - MSM - AMM 25-21-00, 6 -1 - CREW SEATS - Pilot and copilot seats - Check - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 65/11/00/000/000/700 - MSM - AMM 65-11-00, 6 -2 - TAIL ROTOR DRIVE SHAFT - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Drive Shaft - Forward Shaft - Detailed check - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 65/11/00/000/000/650 - MSM - AMM 65-11-00, 6 -1 - TAIL ROTOR DRIVE SHAFT - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Drive Shaft - Damper - Adjustment check - RIG	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 62/21/00/000/000/820 - MSM - AMM 62-21-00, 6 -2 to AMM 62-21-00, 6-25 - MAIN ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Main rotor hub - Detailed check with removal - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 25/22/00/000/000/050 - MSM - AMM 25-22-00, 6 -1 - PASSENGERS SEATS - Aft bench seat - Check - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 29/00/00/000/000/000 - MSM - AMM 29-00-00, 3 -2 - HYDRAULIC POWER - Hydraulic power system - Draining - DRN	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 65/11/00/000/000/400 - MSM - AMM 65-11-00, 6 -7 - TAIL ROTOR DRIVE SHAFT - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Drive Shaft - Splined Flange - Detailed check - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Package	G-LTZY	1500H/72M Inspection 28/12/00/000/000/200 - MSM - AMM 28-12-00, 6 -2 - FUEL SYSTEM - Internal Tanks - Anti-spillage Valve - Check - DI	6 Yrs	19/10/2024	5 Mths 19 Days
Miscellaneous	G-LTZY	REF: G-LTZY/UK.CAMO.0661/28112022 - ARC - Renew	1 Yr	11/12/2024 (+2 Days)	7 Mths 13 Days
Miscellaneous	G-LTZY	REF: P235479/400 - Certificate of Insurance - Renew	1 Yr	22/12/2024	7 Mths 22 Days
Publication	ENG S/N - 34032	2005-088 - AD: F-2005-088 - ASB A319 73 4823 - Check of correct position of adjusted FCU fuel filter - DGAC AD F-2005-088 and ASB A319734823 - Check of the correct position of the adjusted FCU fuel filter	2 Yrs	10/02/2025	9 Mths 10 Days
Miscellaneous	G-LTZY	- Review of Aircraft Maintenance Programme - Carry out review of A/C utilisation for Maintenance Programme (A2B-F-0069).	1 Yr	04/03/2025	10 Mths 4 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Component	G-LTZY	24/33/00/000/000/070 - P/N: 151CH-1 - S/N: D01649 - Battery - MSM - CMM 24-33-96 CHECK § 8 - Battery - Pt No: 150CH-1 (7050A4243027) 151CH-1 (7050A4243040) 151CH-2 (7050A4243039) - Overhaul - DI	2 Yrs	11/04/2025	11 Mths 11 Days
Component	G-LTZY	ICA-3404 - P/N: 011-00455-00 - S/N: 84145863 - Garmin GTX330 Transponder (ICA) - Gama Engineering Ltd Doc: ICA101701 Issue 2, Para 3.3 - Garmin GTX330 Mode S Transponder - Check the correct Mode S address is programmed into the transponder	2 Yrs	10/05/2025	1 Yr 10 Days
Component	G-LTZY	P/N: 421722-8 - S/N: N/A - Steerable Landing Light (ICA) - Carry out functional check iaw AMM 33-44-01,5-1	2 Yrs	10/05/2025	1 Yr 10 Days
Publication	G-LTZY	2011-15 - SIB 2011-15 Rev.2 - Mode S Transponder: Ground Testing - EASA SIB 2011-15 R2 - Mode S and Mode C Transponder Systems; Ground Testing.	2 Yrs	10/05/2025	1 Yr 10 Days
Component	G-LTZY	ICA-3405 - P/N: 011-00455-00 - S/N: 84145863 - Garmin GTX330 Transponder (ICA) - Gama Engineering Ltd Doc: ICA101701 Issue 2, Para 3.4 - Garmin GTX330 Mode S Transponder - (Gillham code transponder interface only): Check the altitude encoder input to the transponder to comply with EASA AD 2006-0265	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/300 - MSM - AMM 64-21-00, 6-9 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Blade assembly - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/270 - MSM - AMM 64-21-00, 6-6 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Outer Bearing - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/320 - MSM - AMM 64-21-00, 6-11 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Top chinese bushing - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/360 - MSM - AMM 64-21-00, 6-15 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Hub Plate - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/330 - MSM - AMM 64-21-00, 6-12 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Bottom chinese bushing - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/260 - MSM - AMM 64-21-00, 6-5 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Splined Flange - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/280 - MSM - AMM 64-21-00, 6-7 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Inner Bearing - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/255 - MSM - AMM 64-21-00, 6-4 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Hub body assembly - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/340 - MSM - AMM 64-21-00, 6-13 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Pitch-change spider - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/350 - MSM - AMM 64-21-00, 6-14 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Fairing Assembly - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/290 - MSM - AMM 64-21-00, 6-8 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Torsion spider assembly - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/370 - MSM - AMM 64-21-00, 6-16 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Thrust washer / Thrust nut / Lockwasher - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	1000H/24M Inspection - (Components) 64/21/00/000/000/310 - MSM - AMM 64-21-00, 6-10 - TAIL ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Hub - Stepped Bolt - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	24M Inspection 53/50/00/000/000/300 - MSM - AMM 53-50-00, 6-2, 53-50-00, 6-3 and 53-50-00, 6-4 - AFT FUSELAGE - Tail boom - Check for corrosion under the antenna bases - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	24M Inspection 34/10/00/000/000/000 - MSM - AMM 34-10-00, 3-1 - NAVIGATION - Pitot-Static System - Bleeding and Drying - FT	2 Yrs	10/05/2025	1 Yr 10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	24M Inspection 62/21/00/000/000/360 - MSM - AMM 62-21-00, 6-9 - MAIN ROTOR HUB - Main Rotor Hub - Upper blade sleeve - Detailed check - Only concerns the aircraft before serial number 1498 and from 8001 to 8029 included not having applied SB 62-004 to the revision 1 - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	24M Inspection 24/33/00/000/000/080 - MSM - AMM 24-33-00, 3-1 - BATTERY - Battery - Pt No: 150CH-1 (7050A4243027) 151CH-1 (7050A4243040) 151CH-2 (7050A4243039) - Battery compartment cleaning - CLN	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	24M Inspection 62/21/00/000/000/410 - MSM - AMM 62-21-00, 6-10 - MAIN ROTOR HUB - Main Rotor Hub - Lower blade sleeve - Detailed check - Only concerns the aircraft before serial number 1498 and from 8001 to 8029 included not having applied SB 62-004 to the revision 1 - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/32/00/000/000/400 - MSM - AMM 62-32-00, 6-5 - FLARED HOUSING / SWASHPLATES / HUB COUPLINGS - (NOTE: SAFETY CRITICAL TASK) - Scissor bolt - Play checks - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 28/00/00/000/000/050 - MSM - AMM 28-00-00, 6-1 - FUEL SYSTEM - Fuel system - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 67/10/00/000/000/050 - MSM - AMM 67-10-00, 6-1 - MAIN ROTOR CONTROLS - Main rotor controls - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 53/53/00/000/000/150 - MSM - AMM 20-10-00, 6-1 and AMM 53-53-00, 4-1 - FENESTRON - (NOTE: SAFETY CRITICAL TASK) - Tail Boom and Fenestron Junction - Tightening torque check - TCK	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 67/20/00/000/000/100 - MSM - AMM 67-20-00, 6-1 - TAIL ROTOR CONTROLS - Tail rotor controls - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/32/00/000/000/350 - MSM - AMM 62-32-00, 6-1 - FLARED HOUSING / SWASHPLATES / HUB COUPLINGS - (NOTE: SAFETY CRITICAL TASK) - "Diapason" scissors - Ball joint - Play check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 24/00/00/000/000/100 - MSM - AMM 24-00-00, 6-1 - ELECTRICAL POWER - Electrical Power Supply System - Inspection - VC	2 Yrs	10/05/2025	1 Yr 10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	500H/24M Inspection 76/11/00/000/000/000 - MSM - AMM 76-11-00, 6-1 - ENGINE CONTROLS - (NOTE: SAFETY CRITICAL TASK) - Engine Controls - Anticipator control - Ball joint - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 28/22/00/000/000/100 - MSM - AMM 28-22-00, 5-1 - FUEL SYSTEM - Fuel Shut-off Valve - Functional test - FT	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/21/00/000/000/790 - MSM - AMM 62-21-00, 6-2 to AMM 62-21-00, 6-20 - MAIN ROTOR HUB - Main rotor hub - Visual check without removal - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 52/50/00/000/000/210 - MSM - AMM 52-50-00, 6-2 & 6-3 - SLIDING DOOR - Cabin Sliding Door - Inspection/Check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 65/21/00/000/000/300 - MSM - AMM 12-10-00, 3-2 - TAIL GEARBOX - TGB - Oil change - DRN	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 52/11/00/000/000/050 - MSM - AMM 52-11-00, 5-1 - RIGHT CABIN DOOR - Jettison System RH Cabin Door - Functional test - FT	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 21/51/00/000/000/250 - MSM - AMM 20-10-00, 6-1 and AMM 21-51-00, 8-1 - COOLING - MGB compressor - Tightening torque check of attachment - TCK	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 21/00/00/000/000/000 - MSM - AMM 21-41-00, 5-1 - AIR CONDITIONING - P2 Indicating System - Functional test - FT - (Very cold weather)	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 71/41/00/000/000/200 - MSM - AMM 71-41-00, 6-1 to AMM 71-41-00, 6-11 - ENGINE SUPPORT BRACKET - (NOTE: SAFETY CRITICAL TASK) - Engine support bracket components - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 05/22/00/000/000/050 - MSM - FLM Section 8 - PREPARATION FOR INSPECTION - Do a Ground Check - GR	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 28/42/00/000/000/150 - MSM - AMM 28-42-00, 6-1 - FUEL SYSTEM - Fuel Low-Level Warning - Check - DI	2 Yrs	10/05/2025	1 Yr 10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	500H/24M Inspection 63/11/00/000/000/150 - MSM - AMM 20-10-00, 6-1 and AMM 63-11-00, 6-6 - MGB / ENGINE COUPLING - (NOTE: SAFETY CRITICAL TASK) - Flexible coupling - Tightening torque check - TCK	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 28/00/00/000/000/060 - MSM - AMM 28-00-00, 6-3 - FUEL SYSTEM - Fuel System - Strainers - Check and cleaning - DI CLN	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 52/10/00/000/000/000 - MSM - AMM 52-10-00, 6-2 / 6-3 / 6-4 - STANDARD CABIN DOORS - Standard Cabin Doors - Inspection/Check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 34/00/00/000/000/050 - MSM - AMM 34-00-00, 6-1 - NAVIGATION - Navigation System - Installation check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/32/00/000/000/360 - MSM - AMM 62-32-00, 6-2 - FLARED HOUSING / SWASHPLATES / HUB COUPLINGS - Scissor link - Check - In the case of default constated inside the rings of the scissor link (inside the limits) make sure of the absences of the following hard points CT 62-32-00, 6-7 every 100 FH (marge 10 FH) - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 52/30/00/000/000/000 - MSM - AMM 52-30-00, 3-1 - LOADING DOORS - Door lock - Pt No: HA2423-3 (706A31610026) - Check and greasing - DI LUB	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/32/00/000/000/370 - MSM - AMM 62-32-00, 6-4 - FLARED HOUSING / SWASHPLATES / HUB COUPLINGS - (NOTE: SAFETY CRITICAL TASK) - Pitch change rod - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 53/30/00/000/000/300 - MSM - AMM 20-10-00, 6-1 and AMM 53-30-00, 4-2 - MAIN FUSELAGE - (NOTE: SAFETY CRITICAL TASK) - MGB suspension bar brackets - Tightening torque check - TCK	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 53/50/00/000/000/250 - MSM - AMM 20-10-00, 6-1 and AMM 53-50-00, 4-1 - AFT FUSELAGE - (NOTE: SAFETY CRITICAL TASK) - Main fuselage and tail boom junction - Tightening torque check - TCK	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 63/52/00/000/000/050 - MSM - AMM 63-52-00, 6-1 - ROTOR BRAKE CONTROL - Rotor brake control - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	500H/24M Inspection 63/51/00/000/000/100 - MSM - AMM 63-51-00, 6-1 - ROTOR BRAKE - Rotor brake - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 21/51/00/000/000/200 - MSM - AMM 21-51-00, 8-1 - COOLING - Belt - Check of tension - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 21/51/00/000/000/150 - MSM - AMM 21-51-00, 6-1 - COOLING - Air conditioning system - Inspection of the installation - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 52/53/00/000/000/000 - MSM - AMM 52-53-00, 5-1 - LEFT SMALL DOOR - Jettison System LH small cabin door - Functional test - FT	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/31/00/000/000/160 - A - MSM - AMM 62-31-00, 6-6 - SWASHPLATE ASSEMBLY - Rotating swashplate - Pt No: 7050A3623019 (7050A3623019) - Inspection of free rotation - Operation to be done every 100 FH (margin 10 FH) between 3300 FH and 5300 FH from the OTL - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 33/00/00/000/000/050 - MSM - AMM 33-00-00, 6-1 - LIGHTING SYSTEMS - Lighting System - Installation check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/21/00/000/000/795 - MSM - AMM 62-21-00, 6-26 - MAIN ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Split Ring - POST SB 62-010 or from SN 1393 and 8009 (factory applied modification) - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 63/22/00/000/000/650 - MSM - AMM 12-10-00, 3-2 and AMM 63-22-00, 3-1 - MGB MAIN MODULE - MGB - Drain and replace the MGB oil filter - DRN	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 65/21/00/000/000/350 - MSM - AMM 20-10-00, 6-1 and AMM 65-21-00, 4-2 - TAIL GEARBOX - TGB / Stator coupling - Tightening torque check - TCK	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 53/00/00/000/000/200 - MSM - AMM 53-00-00, 6-1 and AMM 53-00-00, 6-2 - FUSELAGE - Fuselage - Visual check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 52/50/00/000/000/200 - MSM - AMM 52-50-00, 6-1 - SLIDING DOOR - Cabin Sliding Door - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days



# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	500H/24M Inspection 31/00/00/000/000/050 - MSM - AMM 31-00-00, 6 -1 - INDICATING AND RECORDING SYSTEMS - Indicating and recording system - Check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 76/12/00/000/000/000 - MSM - AMM 12-20-00, 6 -1 - ENGINE CONTROLS - (NOTE: SAFETY CRITICAL TASK) - Engine Controls - Manual Control - Ball end-fitting - L'HOTELLIER - Check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/11/00/000/000/150 - MSM - AMM 62-11-00, 6 -1 - MAIN ROTOR BLADES - Main rotor blade - Inspection - Check every 100 FH (marge 10 FH) for 500 FH, if a defect (inside the limits) is found : blade skin separation or blade leading edge stainless steel strip separation, cracks in the stainless steel leading edge. If no development is noted during this period, return to the normal inspection cycle - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 65/11/00/000/000/800 - MSM - AMM 65-11-00, 6 -3 - TAIL ROTOR DRIVE SHAFT - Tail Rotor Drive Shaft - Damper and contact surface on drive shaft - Check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 76/12/00/000/000/050 - MSM - AMM 76-12-00, 4 -3 - ENGINE CONTROLS - (NOTE: SAFETY CRITICAL TASK) - Engine Controls - Manual Control - Fuel flow ball-type control - Check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/32/00/000/000/300 - MSM - AMM 62-32-00, 3 -1 - FLARED HOUSING / SWASHPLATES / HUB COUPLINGS - Non-rotating and rotating scissors - Carbide rings - Greasing - LUB	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 63/11/00/000/000/100 - MSM - AMM 12-10-00, 6 -1 and AMM 63-11-00, 4-2 - MGB / ENGINE COUPLING - (NOTE: SAFETY CRITICAL TASK) - Ball joint bolt - Tightening torque check - TCK	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 63/00/00/000/000/300 - MSM - AMM 63-00-00, 6 -1 - MAIN ROTOR DRIVE - Main rotor drive - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/31/00/000/000/150 - MSM - AMM 62-31-00, 6 -6 - SWASHPLATE ASSEMBLY - (NOTE: SAFETY CRITICAL TASK) - Rotating swashplate - Inspection of free rotation - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 24/33/00/000/000/100 - MSM - AMM 24-33-00, 5 -1 - BATTERY - Battery temperature detector - Functional test - FT	2 Yrs	10/05/2025	1 Yr 10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	500H/24M Inspection 53/37/00/000/000/000 - MSM - AMM 53-37-00, 6 -1 - CABIN ANTIVIBRATORS - Cabin antivibrator support - Readjustment of the tightening torque - RTQ	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 67/31/00/000/000/150 - MSM - AMM 20-10-00, 6 -1 and AMM 67-31-00, 4-2 - SERVOCONTROLS - Servocontrol - Tightening torque check of the attachment bolts - TCK	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 23/00/00/000/000/050 - MSM - AMM 23-00-00, 6 -1 - COMMUNICATIONS - Communication System - Inspection - VC	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 55/11/00/000/000/000 - MSM - AMM 55-11-00, 6 -1 - HORIZONTAL STABILIZER - (NOTE: SAFETY CRITICAL TASK) - Horizontal Stabilizer - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 65/11/00/000/000/900 - MSM - AMM 65-11-00, 6 -15 - TAIL ROTOR DRIVE SHAFT - (NOTE: SAFETY CRITICAL TASK) - Tail Rotor Drive Shaft - Flexible Coupling Attachment - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 21/00/00/000/000/010 - MSM - AMM 21-21-00, 6 -1 - AIR CONDITIONING - P2 Indicating System - Check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 29/00/00/000/000/050 - MSM - AMM 29-00-00, 6 -1 - HYDRAULIC POWER - Servocontrol - Accumulator - Pressure check - NPT	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/21/00/000/000/840 - MSM - AMM 62-21-00, 6 -28 - MAIN ROTOR HUB - Scissors drive coupling / Main rotor hub - Tightening torque check - TCK	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 88/00/00/000/000/050 - MSM - AMM 88-00-00, 6 -1 - ELECTRICAL HARNESSSES - Electrical harnesses - Check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 65/21/00/000/000/400 - MSM - AMM 65-21-00, 6 -1 - TAIL GEARBOX - TGB - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 79/21/00/000/000/050 - MSM - AMM 79-21-00, 6 -1 - ENGINE OIL COOLING - Engine Oil - Oil cooling system - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	G-LTZY	500H/24M Inspection 62/21/00/000/000/780 - MSM - AMM 62-21-00, 6-2 and AMM 63-21-00, 6-2 - MAIN ROTOR HUB - (NOTE: SAFETY CRITICAL TASK) - Main Rotor Hub - Contact areas between Rotor Shaft and Hub Body - Check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 71/00/00/000/000/100 - MSM - AMM 71-00-00, 6-1 - POWER PLANT - Power plant installation - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 62/11/00/000/000/160 - MSM - AMM 62-11-00, 6-4 - MAIN ROTOR BLADES - Main Rotor Blades - Attachment Components - Detailed check - DI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	G-LTZY	500H/24M Inspection 52/10/00/000/000/100 - MSM - AMM 52-10-00, 6-1 - STANDARD CABIN DOORS - Standard Cabin Door - Condition check - GVI	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	600H/24M Inspection ARS2F - 60001 - 72-00-42-200-804 - No Ref - Centrifugal compressor - Visual inspection of the leading edges	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	600H/24M Inspection ARS2F - 60004 - 73-14-00-700-802 - No Ref - Sealing inspection of the drain valve from the fuel valve assembly - (Ground Run)	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	600H/24M Inspection ARS2F - 60005 - 79-38-00-750-801 - No Ref - Electrical magnetic plugs - Tests	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	600H/24M Inspection ARS2F - 60002 - 73-31-00-750-801 - No Ref - Pre-blockage pressure switch of the fuel filter - Tests - (If P/N different from 9550172880)	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	600H/24M Inspection ARS2F - 60016 - 71-71-00-700-801 - No Ref - Turbine casing drain valve - Tests - (Ground Run)	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	600H/24M Inspection ARS2F - 60006 - 72-00-42-200-802 - No Ref - Free rotation of the gas generator - Manual check	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	600H/24M Inspection ARS2F - 60008 - 73-23-06-900-802 - No Ref - (NOTE: SAFETY CRITICAL TASK) - Removal/Installation of the filtering element of the adjusted fuel control unit	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	600H/24M Inspection ARS2F - 60010 - 12-10-20-610-801 - No Ref - Engine oil change - (Not operating in erosive or fouling atmosphere OR not use of BPTO 2380, ASTO 560 or ROYCO 560)	2 Yrs	10/05/2025	1 Yr 10 Days

# Next Due Work of A/C - G-LTZY



**Date** 30/04/2024  
**AC Hours** 2486 Hrs 8 mn  
**AC Landings** 7878  
**#1 Eng:** 2365 Hrs 26 mn / N1 - 2983.58 / N

**Calendar** 3 Yrs  
**Hours** 500 Hrs  
**Landings** 2000  
**Engine Cy.**

Type	Support	Task Description	Frequency	Support Deadline	Remaining
<b>Calendar</b>					
Package	ENG S/N - 34032	600H/24M Inspection ARS2F - 60003 - 26-12-00-750-801 - No Ref - Test of the fire detector harness	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	500H/24M Inspection ARS2F - 50004 - 73-23-00-700-801 - No Ref - Functional point of the hydromechanical governor - Tests	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	500H/24M Inspection ARS2F - 50002 - 73-15-00-700-801 - No Ref - Non-extinguishing function - Tests - (Ground Run)	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	500H/24M Inspection ARS2F - 50001 - 73-31-00-750-801 - No Ref - Pre-blockage pressure switch of the fuel filter - Tests - (If P/N 9550172880)	2 Yrs	10/05/2025	1 Yr 10 Days
Package	ENG S/N - 34032	500H/24M Inspection ARS2F - 50003 - 73-14-05-750-801 - No Ref - Sealing test of the start electrovalve - (Ground Run)	2 Yrs	10/05/2025	1 Yr 10 Days
Component	G-LTZY	34005-A - P/N: AMP TASK - Compass swing - CAP 562 - Leaflet 5-40 and Leaflet 34-20 - Perform compass swing	2 Yrs	29/09/2025	1 Yr 4 Mths 29 Days
Component	G-LTZY	05/40/00/000/000/010 - P/N: C632A0101052 - S/N: M237 - Epicyclic module (MGB EPICYCLIC MODULE) - MSM - AMM 05-40-00, 6-1 - Dynamic systems - Detailed check - Operation to be carried out after having logged 144 M (margin 180 D) after initial setting to service or since the last Overhaul - DI	6 Yrs	11/08/2026	2 Yrs 3 Mths 11 Days
Component	G-LTZY	05/40/00/000/000/010 - P/N: C632A1110106 - S/N: M188 - Main rotor Shaft (Mast) (MGB EPICYCLIC MODULE) - MSM - AMM 05-40-00, 6-1 - Dynamic systems - Detailed check - Operation to be carried out after having logged 144 M (margin 180 D) after initial setting to service or since the last Overhaul - DI	6 Yrs	11/08/2026	2 Yrs 3 Mths 11 Days
Component	G-LTZY	24/36/01/000/000/050 - P/N: 7050A4243037 - S/N: 1618XL2 - Starter Generator - MSM - 05-10-00 - (NOTE: SAFETY CRITICAL TASK) - Starter generator - Pt No: 160SG140Q-1 (7050A4243037) and 160SG140Q-1-XL (7050A4243050) - SKURKA - Overhaul	5 Yrs	01/10/2026	2 Yrs 5 Mths 1 Day