

AD's/SB's/Task/OOPS					Hrs Due	Hrs to Go	Calendar Frequency	Next Due Date
AD No./SB No. / Task/OOPS	Description	Freq	Last Done	mins				
	Annual Inspection (100 hr items)		8995	45			28/07/23	27/07/24
	Permit Expiry							13/07/24
	6 month		8983	0				27/07/24
	50 hr	50:00	9014	50	9064:50	50:00		
					0:00			
	Radio Licence				0:00			03/02/25
	Rocker Oil levels	25:00	9014	50	9039:50	25:00		
	Oil Change	50:00	9014	50	9064:50	50:00		
					0:00			
	Spark Plugs	50:00	9014	50	9064:50	50:00		
	Oil Pressure Filter Inspection	50:00	9011	5	9061:05	46:15		
EASA AD 2018-0247	Mode S Transponders – Inspection				0:00		NEXT CHECK	
TNS GM 10 No.13 GE No.32	Carburettor & Fuel Pumps Corrosion	100:00	8995	45	9095:45	80:55	'1 Year'	27/07/24
TNS GM 10 No.7	Rocker Pedestal Nuts	100:00	8995	45	9095:45	80:55	'1 Year'	27/07/24
TNS GM 10 No.12	Carburettor Flooding	100:00	8995	45	9095:45	80:55	'1 Year'	27/07/24
TNS GM 10 No. 4	Tappet Clearances	100:00	8995	45	9095:45	80:55	'1 Year'	27/07/24
TNS GE 10 No.16	Magneto Vent screws	100:00	8995	45	9095:45	80:55	'1 Year'	27/07/24
TNS GE 10 No.32	Magneto Timing	100:00	8995	45	9095:45	80:55	'1 Year'	27/07/24
TNS GE 10 No.41 GE No. 15	R/H Magneto Impulse	100:00	8995	45	9095:45	80:55	'1 Year'	27/07/24
TNS GE No. 17	Engine controls wear	100:00	8995	45	9095:45	80:55	'1 Year'	27/07/24
GR24	Engine TBO life extension				0:00			
TNS GM10 No. 50	Mag timing gear oil jets				0:00		'1 Year'	27/07/24
	Oil scavenge filter Inspection				0:00		'1 Year'	27/07/24
CAP 411	Flexible hoses pressure test				0:00		6 years	2019
AD003-08-94 TNS CT [C1] 190 Iss2	Engine Mount Frame Part 'B' - X Ray	600:00	8621	10	9221:10	206:20		
TNS 184, Iss 4	Flap Cables and latch plate	150:00	8995	45	9145:45	130:55	1 Year	27/07/24
CAP 411	Battery Capacity Test				0:00		'1 Year'	27/07/24
TNS 185	Wing Walk Way				0:00		1 Year	27/07/24
TNS 178	Rudder Assy				0:00		1 Year	27/07/24
TNS 177	Aileron Assy - AT AILERON RECOVER, done 12/7/16				0:00			
AD 014-11-97 TNS CT [C1] 176 Iss 1 para 4-3 (post mod 357)	Tail BKT Fatigue - LIFE				0:00		1 Year'	27/07/24
G-2012-0001 TNS CT [C1] 138 Iss 5	Fatigue Hrs Recording				0:00		1 Year'	27/07/24
CAP 562 Lft 51-50 & 51-60	Corrosion of Aircraft Structures				0:00		1 year	27/07/24
CAP 562 Lft 11-22 B180App 31	Altimeter Barometric Adj Knobs				0:00		1 year	27/07/24
TNS 121	Battery Bay				0:00		1 Year	27/07/24
TNS 145	Wheel brake control cable eye end in cockpit - See TNS				0:00		1 Year	27/07/24
TNS 139	Elevator Controls	150:00	8936	5	9086:05	71:15		
GR 8 [ASB56]	Fabric covering				0:00		1 year	27/07/24
	Inspect Rudder Cables beneath Battery Box				0:00		1 year	27/07/24
TNS 141	Elevator Lay Shaft Bracket	150:00	8936	5	9086:05	71:15		
CAP 562 Leaflet B190	CO Contamination				0:00		1 year	27/07/24
	Differential Compression Test	100:00	8995	45	9095:45	80:55	1 year	27/07/24
TNS GE 10 No.42	General Maintenance items	150:00	8995	45	9145:45	130:55	'1 Year'	27/07/24
TNS 150	Elevator Trim Cables				0:00		'1 Year'	27/07/24
					0:00			
AD005-05-90 TNS CT [C1] 183 Iss 4	Fwd Face of AFT Fuselage Frame Cracks	200:00	8995	45	9195:45	180:55	1 year	27/07/24
TNS 152	Tail Wheel Yoke Bolt	150:00	8918	20	9068:20	53:30		
TNS 157	Tail Unit Inspections				0:00		6 Years	29/04/28
TNS 158	Fuselage Structure Inspections				0:00		1 year	27/07/24
TNS 166, Iss 4	Wing Flap Inspection of Root Rib for cracks	300:00	9011	5	9311:05	296:15	6 year	27/07/29
TNS 168	Visual Inspection of engine frame welded joints	50:00	8989	55	9039:55	25:05		
	Rear Engine mount adjusting sleeve cracking (see TNS Para 3.2)	300:00	8891	30	9191:30	176:40		
TNS 156	Fin Structure	600:00	8936	5	9536:05	521:15	3 Years	26/04/25
TNS 122	Elevator outer hinge Rivets						1 Year	27/07/24
AD2220 Pre 80 SB FRP.001.1	Propeller - crack check / balance	300:00	8832	20	9132:20	117:30		
TNS GM10 No. 49	Dye pen prop vernier lockplate	300:00	8832	20	9132:20	117:30		
TNS 159	Control Box Rear Member Cracks	600:00	8521	0	9121:00	106:10		
AD009-09-85 / TNS 180	Engine Mount Frame, inspection of external skin, see TNS				0:00		3 years	26/04/25
TNS 170 ISS 2	Flap layshaft & Operating Cams				0:00		1 year	27/07/24
CAP 411	VSWR on antenna				0:00		3 years	29/04/25
CAP 411	Bonding Checks				0:00		3 years	29/04/25
CAP 411	Compass Swing				0:00		3 years	29/04/25
					0:00			
AD021-08-91 TNS C1 [C1] 186 Iss 2	Tail plane support struts X Ray - NDT				0:00		7 years	18/11/28
AD2280 Pre 80 TNS CT [C1] 199 Iss 3 Parts A & B	Flap Centre Brkts - PART A internal visual (Removed)				0:00		6 years	April 2023
AD2807 Pre 80 Rev 1 TNS CT [C1] 165 Iss 6	MLG Casting X ray				0:00		6 years	15/06/26
					0:00			
ACES 1392	Aeroquip Hoses - LIFE				0:00		10 years	22/02/29
	Engine TBO	1500:00	8933	35	10433:35	1418:45	20 years	22/02/39
					0:00			
TNS 168	Engine Mounting. Replace Bolts & check for cracks - AT ENGINE CHANGE		8936	5	8936:05			
	Prop Overhaul	1000:00	8832	20	9832:20	817:30		
2806 Pre 80/TNS 161	Wing to fuselage attachment link clearance				0:00		Next wing remove/refit	
					0:00			
					0:00			